



序号	报告编号	发布日期	结论	影像资料
12	GX-B1404/20-2-23035	2023. 10. 9	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
13	GX-B1404/20-2-23036	2023. 10. 9	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	

14	GX-B1598/21-2-23103	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.44%，小于5%为正常。	
15	GX-B1598/21-2-23104	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.50%，小于5%为正常。	

16	GX-B1598/21-2-23105	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.66%，小于5%为正常。	
17	GX-B1598/21-2-23106	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.57%，小于5%为正常。	

18	GX-B1598/21-2-23107	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.55%，小于5%为正常。	
19	GX-B1598/21-2-23108	2023. 10. 7	实测钢丝绳有效截面积损失百分比最大为0.46%，小于5%为正常。	

20	GX-B1517/20-2-23034	2023. 10. 10	综合判定：合格	
21	GX-B1517/20-2-23035	2023. 10. 10	综合判定：合格	

22	GX-B1517/20-2-23036	2023. 10. 10	综合判定：合格	
23	GX-B1310/21-2-23220	2023/10/8	符合标准要求。	

24	GX-B1427/21-2-23220	2023/10/8	符合标准要求。	
25	GX-B1416/22-2-23058	2023. 10. 10	综合判定：合格	

26	GX-B1339/21-2-23004	2023/10/12	所检项目合格。	 <p>A photograph showing two workers in a factory setting. One worker in a dark jacket is standing and observing, while another in a light shirt is leaning over a large green industrial machine. The machine has various pipes and components. A date stamp '2023/08/30' is visible in the bottom right corner of the photo.</p>
27	GX-B1339/21-2-23005	2023/10/12	所检项目合格。	 <p>A photograph of a large industrial machine, possibly a generator or motor, with a white cylindrical component. A worker in a dark uniform is standing nearby, looking at the machine. The machine is mounted on a wooden pallet. A date stamp '2023/08/30' is visible in the bottom right corner of the photo.</p>