

序号	报告编号	发布日期	结论	影像资料
121	GX-B1423/20/6-231120	2023/11/24	综合判定合格	 A photograph showing two men wearing red hard hats and safety jackets standing in front of a red HUMAN ETX truck. The truck's license plate is 1Q 376PB. A timestamp in the bottom right corner of the photo reads '2023 11 24'.
122	GX-B1423/20/6-231121	2023/11/24	综合判定合格	 A photograph showing two men wearing red hard hats and safety jackets standing in front of a red truck. The truck's license plate is 1Q 327BL. A timestamp in the bottom right corner of the photo reads '2023 11 24'.

123	GX-B1423/20/6-231122	2023/11/24	综合判定合格	
124	GX-B1328/20-6-23150	2023/11/6	本次共检绝缘手套80只，80只绝缘手套所检项目合格。	
125	GX-B1328/20-6-23151	2023/11/20	本次共检绝缘鞋80只，80只绝缘鞋所检项目合格。	

126	GX-B1423/20-6-231087	2023/11/23	综合判定：合格	 A photograph showing two men in work clothes and safety helmets standing in front of a green truck. The truck has 'ETL' and a logo on the front. A red circle with the number '8' is visible on the side of the truck. A date stamp '2023 11 10' is at the bottom right.
127	GX-B1423/20-6-231088	2023/11/23	综合判定：合格	 A photograph showing a man in a grey work suit and a red safety helmet sitting in the driver's seat of a green truck. He is looking at a device in his hands. A date stamp '2023 11 10' is at the bottom right.
128	GX-B1423/20-6-231089	2023/11/23	综合判定：合格	 A photograph showing two men in work clothes and safety helmets standing in front of a green truck. The truck has '中国重汽' (China Heavy Duty) and the number '22' on its side. A date stamp '2023 11 10' is at the bottom right.

129	GX-B1423/20-6-231090	2023/11/23	综合判定：合格	
130	GX-B1423/20-6-231091	2023/11/23	综合判定：合格	
131	GX-B1423/20-6-231092	2023/11/23	综合判定：合格	


132	GX-B1423/20-6-231093	2023/11/23	综合判定：合格	
133	GX-B1423/20-6-231094	2023/11/23	综合判定：合格	
134	GX-B1423/20-6-231095	2023/11/23	综合判定：合格	



135	GX-B1423/20-6-231096	2023/11/23	综合判定：合格	 A photograph showing two men in work clothes and safety helmets standing next to a green truck. The man on the left wears a red helmet and a grey uniform. The man on the right wears a yellow helmet and a dark blue jacket. The truck has several safety warning signs on its side, including one with the number '7'. A date stamp '2023 11 10' is visible at the bottom right of the photo.
136	GX-B1423/20-6-231097	2023/11/23	综合判定：合格	 A photograph showing a man in a grey uniform and a red helmet sitting in the driver's seat of a green truck, operating the vehicle. The interior of the truck is visible, including the steering wheel and dashboard. A date stamp '2023 11 10' is visible at the bottom right of the photo.
137	GX-B1423/20-6-231098	2023/11/23	综合判定：合格	 A photograph showing two men in work clothes and safety helmets standing next to a green truck. The man on the left wears a red helmet and a grey uniform. The man on the right wears a yellow helmet and a grey uniform. The truck has several safety warning signs on its side, including one with the number '10'. A date stamp '2023 11 11' is visible at the bottom right of the photo.

138	GX-B1423/20-6-231099	2023/11/23	综合判定：合格	 <p>2023 11 11</p>
139	GX-B1423/20-6-231100	2023/11/23	综合判定：合格	 <p>2023 11 11</p>
140	GX-B1423/20-6-231101	2023/11/23	综合判定：合格	 <p>2023 11 11</p>

141	GX-B1423/20-6-231102	2023/11/23	综合判定：合格	
142	GX-B1423/20-6-231103	2023/11/23	综合判定：合格	
143	GX-B1539/22-6-23001	2023/11/23	所检项目合格	

144	GX-B1539/22-6-23002	2023/11/23	所检项目合格	
145	GX-B1539/22-6-23003	2023/11/23	所检项目合格	
146	GX-B1539/22-6-23004	2023/11/23	所检项目合格	

147	GX-B1539/22-6-23005	2023/11/23	所检项目合格	
148	GX-B1539/22-6-23006	2023/11/23	所检项目合格	
149	GX-B1328/20-6-23157	2023/11/27	所检项目合格	

150	GX-B1328/20-6-23158	2023/11/27	所检项目合格	
151	GX-B1328/20-6-23152	2023/11/20	所检项目合格	
152	GX-B1328/20-6-23153	2023/11/27	所检项目合格	

153	GX-B1328/20-6-23154	2023/11/27	所检项目合格	
154	GX-B1328/20-6-23155	2023/11/27	所检项目合格	
155	GX-B1328/20-6-23156	2023/11/27	所检项目合格	

156	GX-B1520/20-6-23113	2023/11/28	综合判定合格	
157	GX-B1520/20-6-23114	2023/11/28	综合判定合格	
158	GX-B1520/20-6-23115	2023/11/28	综合判定合格	

159	GX-B1520/20-6-23116	2023/11/28	综合判定合格	
160	GX-B1520/20-6-23117	2023/11/28	综合判定合格	
161	GX-B1520/20-6-23118	2023/11/28	综合判定合格	

162	GX-B1598/21-6-23055	2023/11/29	实测钢丝绳有效截面积损失百分比最大为1.43%，小于5%为正常。	
163	GX-B1598/21-6-23056	2023/11/29	实测钢丝绳有效截面积损失百分比最大为1.22%，小于5%为正常。	
164	GX-B1598/21-6-23057	2023/11/29	实测钢丝绳有效截面积损失百分比最大为0.76%，小于5%为正常。	

165	GX-B1598/21-6-23058	2023/11/29	实测钢丝绳有效截面积损失百分比最大为1.36%，小于5%为正常。	
166	GX-B1598/21-6-23059	2023/11/29	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	
167	GX-B1598/21-6-23060	2023/11/29	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。	

168	GX-B1423/20-6-231123	2023/11/30	综合判定合格	
169	GX-B1423/20-6-231124	2023/11/30	综合判定合格	
170	GX-B1423/20-6-231125	2023/11/30	综合判定合格	

171	GX-B1423/20-6-231126	2023/11/30	综合判定合格	
172	GX-B1423/20-6-231127	2023/11/30	综合判定合格	
173	GX-B1423/20-6-231128	2023/11/30	综合判定合格	

174	GX-B1423/20-6-231129	2023/11/30	综合判定合格	
175	GX-B1423/20-6-231130	2023/11/30	综合判定合格	
176	GX-B1423/20-6-231131	2023/11/30	综合判定合格	

177	GX-B1423/20-6-231132	2023/11/30	综合判定合格	
178	GX-B1423/20-6-231133	2023/11/30	综合判定合格	
179	GX-B1423/20-6-231134	2023/11/30	综合判定合格	



180	GX-B1423/20-6-231136	2023/11/30	综合判定合格	
181	GX-B1423/20-6-231137	2023/11/30	综合判定合格	
182	GX-B1423/20-6-231138	2023/11/30	综合判定合格	

183	GX-B1423/20-6-231139	2023/11/30	综合判定合格	
184	GX-B1423/20-6-231140	2023/11/30	综合判定合格	
185	GX-B1423/20-6-231141	2023/11/30	综合判定合格	

186	GX-B1423/20-6-231142	2023/11/30	综合判定合格	
187	GX-B1423/20-6-231143	2023/11/30	综合判定合格	
188	GX-B1423/20-6-231144	2023/11/30	综合判定合格	

189	GX-B1423/20-6-231145	2023/11/30	综合判定合格	
190	GX-B1423/20-6-231146	2023/11/30	综合判定合格	
191	GX-B1423/20-6-231147	2023/11/30	综合判定合格	

192	GX-B1423/20-6-231148	2023.11.27	综合判定：合格	
193	GX-B1423/20-6-231149	2023.11.27	综合判定：合格	
194	GX-B1423/20-6-231150	2023.11.27	综合判定：合格	

195	GX-B1423/20-6-231151	2023.11.27	综合判定：合格	
196	GX-B1423/20-6-231152	2023.11.27	综合判定：合格	
197	GX-B1423/20-6-231153	2023.11.27	综合判定：合格	

198	GX-B1423/20-6-231154	2023.11.27	综合判定：合格	 <p>2023 11 15</p>
199	GX-B1423/20-6-231155	2023.11.27	综合判定：合格	 <p>2023 11 15</p>
200	GX-B1423/20-6-231156	2023.11.27	综合判定：合格	 <p>2023 11 15</p>

201	GX-B1423/20-6-231157	2023.11.27	综合判定：合格	
202	GX-B1423/20-6-231158	2023.11.27	综合判定：合格	
203	GX-B1423/20-6-231159	2023.11.27	综合判定：合格	

204	GX-B1423/20-6-231160	2023.11.27	综合判定：合格	
205	GX-B1423/20-6-231161	2023.11.27	综合判定：合格	
206	GX-B1423/20-6-231162	2023.11.27	综合判定：合格	




207	GX-B1328/20-6-23159	2023/11/29	本次共检绝缘手套14只，14只绝缘手套所检项目合格。	
208	GX-B1328/20-6-23160	2023/11/29	本次共检全橡胶绝缘胶靴10只，10只全橡胶绝缘胶靴所检项目合格。	
209	GX-B1598/21-6-23061	2023/11/30	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5%为正常。	

210	GX-B1598/21-6-23062	2023/11/30	<p>实测钢丝绳有效截面积损失百分比最大为1.94%，小于5%为正常。</p>			
211	GX-B1598/21-6-23063	2023/11/30	<p>实测钢丝绳有效截面积损失百分比最大为1.15%，小于5%为正常。</p>			
212	GX-B1598/21-6-23064	2023/11/30	<p>实测钢丝绳有效截面积损失百分比最大为2.44%，小于5%为正常。</p>			


213	GX-B1598/21-6-23065	2023/11/30	实测钢丝绳有效截面积损失百分比最大为0.89%，小于5%为正常。	
214	GX-B1598/21-6-23066	2023/11/30	实测钢丝绳有效截面积损失百分比最大为0.92%，小于5%为正常。	
215	GX-B1598/21-6-23067	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.60%，小于5%为正常。	

216	GX-B1598/21-6-23068	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.08%，小于5%为正常。	 2023 11 23
217	GX-B1598/21-6-23069	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.98%，小于5%为正常。	 2023 11 23
218	GX-B1598/21-6-23070	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。	 2023 11 23

219	GX-B1598/21-6-23071	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.99%，小于5%为正常。	
220	GX-B1598/21-6-23072	2023/11/30	实测钢丝绳有效截面积损失百分比最大为4.64%，小于5%为正常。	
221	GX-B1598/21-6-23073	2023/11/30	实测钢丝绳有效截面积损失百分比最大为3.73%，小于5%为正常。	

222	GX-B1598/21-6-23074	2023/11/30	实测钢丝绳有效截面积损失百分比最大为2.23%，小于5%为正常。	
223	GX-B1598/21-6-23075	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.43%，小于5%为正常。	
224	GX-B1598/21-6-23076	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.31%，小于5%为正常。	

225	GX-B1598/21-6-23077	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.04%，小于5%为正常。	
226	GX-B1598/21-6-23078	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.78%，小于5%为正常。	
227	GX-B1598/21-6-23079	2023/11/30	实测钢丝绳有效截面积损失百分比最大为0.95%，小于5%为正常。	

228	GX-B1598/21-6-23080	2023/11/30	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常。	
-----	---------------------	------------	----------------------------------	---