


序号	报告编号	发布日期	结论	影像资料
56	GX-B1328/20-2-24092	2024/10/16	本次共检验电器16支，16支所检项目合格。	 A photograph showing a worker in a blue shirt and red helmet standing in a room. There is a desk with a computer monitor, a chair, and various electrical equipment on the floor. A date stamp '2024/09/29' is visible in the bottom right corner of the image.
57	GX-B1328/20-2-24093	2024/10/16	本次共检携带式接地和接地短路装置16组，16组所检项目合格。	 A photograph showing a worker in a blue shirt and red helmet kneeling on the floor, working with electrical equipment. There is a desk with a computer monitor, a chair, and various electrical equipment on the floor. A date stamp '2024/09/29' is visible in the bottom right corner of the image.

58	GX-B1328/20-2-24094	2024/10/16	本次共检绝缘杆1组，1组所检项目合格。	
59	GX-B1328/20-2-24099	2024/10/18	本次共检验电器2支，2支所检项目合格。	
60	GX-B1328/20-2-24100	2024/10/18	本次共检携带式接地和接地短路装置20组，20组所检项目合格。	

61	GX-B1328/20-2-24101	2024/10/18	本次共检绝缘杆4组，4组所检项目合格。	
62	GX-B1328/20-2-24102	2024/10/18	本次共检绝缘胶垫60块，60块所检项目合格。	

63	GX-B1328/20-2-24105	2024. 10. 21	所检项目合格。	
64	GX-B1328/20-2-24106	2024. 10. 21	所检项目合格。	

65	GX-B1328/20-2-24107	2024. 10. 21	所检项目合格。	
66	GX-B1328/20-2-24108	2024. 10. 21	所检项目合格。	

67	GX-B1515/22-2-24013	2024.10.22	所检项目合格。	 <p>2024-10-09</p>
68	GX-B1328/20-2-24082	2024.10.25	本次共检绝缘手套18只，18只所检项目合格。	 <p>2024/09/02</p>

69	GX-B1598/24-2-24214	2024.10.25	实测钢丝绳有效截面积损失百分比最大为2.18%，小于5%为正常。	
70	GX-B1598/24-2-24215	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常。	

71	GX-B1598/24-2-24216	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.96%，小于5%为正常。	
72	GX-B1598/24-2-24217	2024.10.25	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常。	

73	GX-B1598/24-2-24218	2024.10.25	实测钢丝绳有效截面积损失百分比最大为0.91%，小于5%为正常。	
74	GX-B1598/24-2-24219	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.10%，小于5%为正常。	

75	GX-B1598/24-2-24220	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。	
76	GX-B1598/24-2-24221	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为0.88%，小于5%为正常。	

77	GX-B1598/24-2-24222	2024.10.25	实测钢丝绳有效截面积损失百分比最大为0.94%，小于5%为正常。	
78	GX-B1598/24-2-24223	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.18%，小于5%为正常。	

79	GX-B1598/24-2-24224	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为2.07%，小于5%为正常。	
80	GX-B1598/24-2-24225	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为2.18%，小于5%为正常。	

81	GX-B1598/24-2-24226	2024.10.25	实测钢丝绳有效截面积损失百分比最大为2.35%，小于5%为正常。	 <p>2024/10/3</p>
82	GX-B1598/24-2-24227	2024.10.25	实测钢丝绳有效截面积损失百分比最大为2.08%，小于5%为正常。	 <p>2024/10/3</p>

83	GX-B1598/24-2-24228	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.86%，小于5%为正常。	
84	GX-B1598/24-2-24229	2024.10.25	实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常。	

85	GX-B1598/24-2-24230	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为1.66%，小于5%为正常。	
86	GX-B1598/24-2-24231	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常。	

87	GX-B1598/24-2-24232	2024. 10. 25	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常。	 <p>2024/10/25</p>
88	GX-B1310/21-2-24339	2024. 10. 27	符合标准要求。	 <p>2024/10/27</p>

89	GX-B1427/21-2-24339	2024.10.27	符合标准要求。	
90	GX-B1310/21-2-24345	2024.10.27	符合标准要求。	

91	GX-B1310/21-2-24346	2024. 10. 27	符合标准要求。		 A worker in a red protective suit and helmet is working on a large green industrial machine. The worker is holding a tool and appears to be inspecting or adjusting a component. The machine has a large red circular part. The date '2024/10/27' is visible in the bottom right corner of the image.	
92	GX-B1310/21-2-24347	2024. 10. 27	符合标准要求。		 A worker in a blue protective suit and helmet is working in a dark industrial environment. The worker is standing near some equipment and appears to be inspecting or working on it. The date '2024/10/8' is visible in the bottom right corner of the image.	

93	GX-B1310/21-2-24348	2024. 10. 27	符合标准要求。	 <p>2024/10/9</p>
94	GX-B1310/21-2-24349	2024. 10. 27	符合标准要求。	 <p>2024/10/9</p>

95	GX-B1310/21-2-24350	2024. 10. 27	符合标准要求。	 <p>2024/10/8</p>
96	GX-B1427/21-2-24350	2024. 10. 27	符合标准要求。	 <p>2024/10/8</p>

97	GX-B1310/21-2-24351	2024. 10. 27	符合标准要求。	
98	GX-B1427/21-2-24351	2024. 10. 27	符合标准要求。	

99	GX-B1310/21-2-24353	2024. 10. 27	符合标准要求。	 A photograph showing a worker in a red protective suit and helmet standing on a metal platform in an industrial setting. The worker is holding a tool or device. The background shows industrial machinery and structures. A timestamp "2024/10/27" is visible in the bottom right corner of the image.
100	GX-B1427/21-2-24353	2024. 10. 27	符合标准要求。	 A photograph showing a worker in a red protective suit and helmet standing on a metal platform in an industrial setting. The worker is holding a tool or device. The background shows industrial machinery and structures. A timestamp "2024/10/27" is visible in the bottom right corner of the image.

101	GX-B1310/21-2-24354	2024. 10. 27	符合标准要求。	
102	GX-B1427/21-2-24354	2024. 10. 27	符合标准要求。	

103	GX-B1310/21-2-24355	2024.10.27	符合标准要求。	
104	GX-B1301/23-2- 24009	2024.10.29	综合判定：合格。	

105	GX-B1310/21-2-24342	2024/10/29	符合标准要求。	
106	GX-B1310/21-2-24343	2024/10/29	符合标准要求。	

107	GX-B1310/21-2-24344	2024/10/29	符合标准要求。	
108	GX-B1598/24-2-24239	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.73%，小于5%为正常。	

109	GX-B1598/24-2-24240	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.79%，小于5%为正常。	
110	GX-B1598/24-2-24241	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.54%，小于5%为正常。	

111	GX-B1598/24-2-24242	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.65%，小于5%为正常。	
112	GX-B1598/24-2-24243	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.03%，小于5%为正常。	

113	GX-B1598/24-2-24244	2024/10/29	实测钢丝绳有效截面积损失百分比最大为1.19%，小于5%为正常。	
114	GX-B1310/21-2-24340	2024/10/29	符合标准要求。	

115	GX-B1310/21-2-24341	2024/10/29	符合标准要求。	 <p>2024/09/29</p>
116	GX-B1495/20-2-241475~241476	2024/10/29	本次共检高压交流断路器2台，2台所检项目合格。	 <p>2024/10/29</p>

117	GX-B1495/20-2-241477	2024/10/29	所检项目合格。	 2024/10/11
118	GX-B1329/21-2-24009~24024	2024/10/29	本次共检氧化锌避雷器16组，16组所检项目合格。	 2024/10/12