

序号	报告编号	发布日期	结论	影像资料
9	GX-B1310/21-Z-22031	2022/6/8	符合标准要求	 <p>A photograph showing a worker in an orange safety vest and helmet inspecting a large, red, cylindrical industrial component. The component has a complex internal structure with multiple blades or vanes. A date stamp '2022.05.31' is visible in the bottom right corner of the image.</p>
10	GX-B1310/21-Z-22032	2022/6/8	符合标准要求	 <p>A photograph showing a worker in an orange safety vest and helmet inspecting a large, red, cylindrical industrial component. The component has a complex internal structure with multiple blades or vanes. A date stamp '2022.05.31' is visible in the bottom right corner of the image.</p>
11	GX-B1310/21-Z-22033	2022/6/8	符合标准要求	 <p>A photograph showing a worker in an orange safety vest and helmet inspecting a large, red, cylindrical industrial component. The component has a complex internal structure with multiple blades or vanes. A date stamp '2022.05.31' is visible in the bottom right corner of the image.</p>

12	GX-B1428/21-Z-22001	2022/6/8	符合标准要求		
13	GX-B1322 / 21-Z-22008~22009	2022/6/10	所检项目合格		