





序号	报告编号	发布日期	结论	影像资料
130	GX-B1451/20-2-22181~22183	2022. 7. 7	合格	 <p>2022/6/15</p>
131	GX-B1336/22-2-22001~22002	2022. 7. 8	合格	 <p>2022/6/15</p>

132	GX-B1495/20-2-22640~22651	2022. 7. 8	合格	
133	GX-B1495/20-2-22652~22663	2022. 7. 8	合格	
134	GX-B1310/21-2-22107	2022. 7. 6	合格	

135	GX-B1428/21-2-22107	2022. 7. 6	合格	
136	GX-B1310/21-2-22108	2022. 7. 6	合格	
137	GX-B1428/21-2-22108	2022. 7. 6	合格	

138	GX-B1313/21-2-22062~22073	2022. 7. 7	合格	
139	GX-B1350/21-2- 22059	2022. 7. 8	合格	

140	GX-B1350/21-2- 22060	2022. 7. 8	合格	 <p>A photograph showing a worker in a bright orange jumpsuit and a red hard hat. The worker is kneeling on the ground in a dark, confined space, possibly a tunnel or underground facility. They are focused on a piece of equipment or a cable. A bright light source, likely a headlamp or a work light, illuminates the worker and the equipment. The background is dark and indistinct. A small timestamp '2022/6/9' is visible in the bottom right corner of the photo.</p>
141	GX-B1313/21-2-22059~22061	2022. 7. 7	合格	 <p>A photograph of a worker standing in an industrial or utility setting. The worker is wearing a light blue short-sleeved shirt, dark pants, black boots, and a red hard hat. They are standing next to a large piece of equipment that has two prominent red cylindrical tanks. To the right of the worker is a red fire extinguisher on a small cart. The background shows a plain wall and some equipment. A small timestamp '2022/6/15' is visible in the bottom right corner of the photo.</p>

142	GX-B1322/21-2-22128~22130	2022. 7. 7	合格	
-----	---------------------------	------------	----	---