

序号	报告编号	发布日期	结论	影像资料
372	GX-B1310/21-1-22064	2022/7/5	合格	
373	GX-B1310/21-1-22065	2022/7/5	合格	
374	GX-B1310/21-1-22066	2022/7/5	合格	
375	GX-B1310/21-1-22067	2022/7/5	合格	
376	GX-B1310/21-1-22068	2022/7/5	合格	
377	GX-B1428/21-1-22067	2022/7/5	合格	

378	GX-B1428/21-1-22068	2022/7/5	合格	
379	GX-B1423/20-1-22231	2022/7/15	合格	
380	GX-B1423/20-1-22232	2022/7/15	合格	
381	GX-B1423/20-1-22233	2022/7/15	合格	

382	GX-B1423/20-1-22234	2022/7/15	合格	
383	GX-B1423/20-1-22235	2022/7/15	合格	
384	GX-B1423/20-1-22236	2022/7/15	合格	
385	GX-B1423/20-1-22237	2022/7/15	合格	

386	GX-B1423/20-1-22238	2022/7/15	合格	
387	GX-B1423/20-1-22239	2022/7/15	合格	
388	GX-B1423/20-1-22240	2022/7/15	合格	
389	GX-B1423/20-1-22241	2022/7/15	合格	

390	GX-B1423/20-1-22242	2022/7/15	合格	
391	GX-B1423/20-1-22221	2022/7/15	合格	
392	GX-B1423/20-1-22222	2022/7/15	合格	
393	GX-B1423/20-1-22223	2022/7/15	合格	

394	GX-B1423/20-1-22224	2022/7/15	合格	 A yellow truck with the number 04 on its front. Two men are standing in front of it: one in a blue uniform and another in a grey uniform. The date 2022.06.27 is visible at the bottom of the photo.
395	GX-B1423/20-1-22225	2022/7/15	合格	 A yellow truck with the number 05 on its front. Two men are standing in front of it: one in a blue uniform and another in a grey uniform. The date 2022.06.27 is visible at the bottom of the photo.
396	GX-B1423/20-1-22226	2022/7/15	合格	 A yellow truck with a large dump body. Two men are standing in front of it: one in a blue uniform and another in a grey uniform. The date 2022.06.27 is visible at the bottom of the photo.
397	GX-B1423/20-1-22227	2022/7/15	合格	 A yellow truck with the number 07 on its front. Two men are standing in front of it: one in a blue uniform and another in a grey uniform. The date 2022.06.27 is visible at the bottom of the photo.

398	GX-B1423/20-1-22228	2022/7/15	合格	 A yellow dump truck with the number '08' on its front. Two workers in blue and grey uniforms are standing in front of the truck. The date '2022.06.27' is visible in the bottom right corner of the photo.
399	GX-B1423/20-1-22229	2022/7/15	合格	 A yellow dump truck with the number '09' on its front. Two workers in blue and grey uniforms are standing in front of the truck. The date '2022.06.27' is visible in the bottom right corner of the photo.
400	GX-B1423/20-1-22230	2022/7/15	合格	 A yellow dump truck with the number '10' on its front. Two workers in blue and grey uniforms are standing in front of the truck. The date '2022.06.27' is visible in the bottom right corner of the photo.
401	GX-B1306/21-1-22041	2022/7/13	合格	 Two workers in grey uniforms are inspecting a white air compressor. The compressor has 'OGFD-202 ID AIR COMPRESSOR' written on it. The date '2022/06/05' is visible in the bottom right corner of the photo.

402	GX-B1306/21-1-22042	2022/7/13	合格	 A person wearing a white long-sleeved shirt and green gloves is working on a piece of equipment. Another person in a blue shirt is visible in the foreground, looking towards the equipment. A yellow timestamp '2022/06/05' is visible on the left side of the image.
403	GX-B1306/21-1-22043	2022/7/13	合格	 Two people are standing in a hallway, looking at a large blue panel. One person is wearing a white jacket and the other is wearing a blue and white striped shirt. A yellow timestamp '2022/06/05' is visible in the bottom right corner of the image.
404	GX-B1306/21-1-22044	2022/7/13	合格	 Two people are standing in a room, looking at a large blue panel. One person is wearing a white jacket and the other is wearing a blue and white striped shirt. A yellow timestamp '2022/06/05' is visible in the bottom right corner of the image.