






序号	报告编号	发布日期	结论	影像资料
249	GX-B1548/20-1-22009	2022/8/30	合格	 A person wearing a blue t-shirt, black shorts, and a red hard hat is standing next to an orange vehicle. They appear to be inspecting or working on the side of the vehicle. A toolbox is on the ground nearby. The photo has a timestamp '2022 08 30'.
250	GX-B1548/20-1-22010	2022/8/30	合格	 A person wearing a blue t-shirt, black shorts, and a red hard hat is standing in front of an orange vehicle. They are pointing towards the front of the vehicle. A toolbox is on the ground. The photo has a timestamp '2022 08 30'.
251	GX-B1537/20-1-22007	2022/8/30	合格	 A person wearing a blue t-shirt, black shorts, and a red hard hat is standing next to a red vehicle. They appear to be inspecting the vehicle. A toolbox is on the ground. The photo has a timestamp '2022 08 30'.

252	GX-B1416/22-1-22035	2022/8/29	合格			
253	GX-B1416/22-1-22036	2022/8/29	合格			
254	GX-B1416/22-1-22037	2022/8/29	合格			
255	GX-B1416/22-1-22038	2022/8/29	合格			
256	GX-B1416/22-1-22040	2022/8/29	合格			

257	GX-B1534/20-1-22008	2022/8/31	合格	 A photograph showing the rear view of a yellow dump truck. A person is standing near the truck, and a small blue and black object is on the ground in front of it. A red vertical stamp on the right side of the image reads "2022 08 31".
258	GX-B1534/20-1-22009	2022/8/31	合格	 A photograph showing the rear view of a yellow dump truck. A person is standing near the truck, and a small blue and black object is on the ground in front of it. A red vertical stamp on the right side of the image reads "2022 08 31".