

序号	报告编号	发布日期	结论	影像资料
1	GX-B1534/20-2-23013	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>
2	GX-B1534/20-2-23014	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>
3	GX-B1534/20-2-23015	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>

4	GX-B1534/20-2-23016	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>
5	GX-B1534/20-2-23017	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>
6	GX-B1534/20-2-23018	2023. 7. 1	所检项目合格。	 <p>2023/06/12</p>

7	GX-B1534/20-2-23019	2023. 7. 1	所检项目合格。	
8	GX-B1500/21-2-23062	2023. 7. 1	综合判定:合格。	
9	GX-B1500/21-2-23063	2023. 7. 1	综合判定:合格。	

10	GX-B1500/21-2-23064	2023. 7. 1	综合判定:合格。			
11	GX-B1500/21-2-23065	2023. 7. 1	综合判定:合格。			
12	GX-B1500/21-2-23066	2023. 7. 1	综合判定:合格。			

13	GX-B1500/21-2-23067	2023. 7. 1	综合判定:合格。			
14	GX-B1416/22-2-23020	2023. 7. 3	综合判定:合格。			
15	GX-B1416/22-2-23021	2023. 7. 3	综合判定:合格。			




16	GX-B1416/22-2-23022	2023. 7. 3	综合判定：合格。			
17	GX-B1416/22-2-23023	2023. 7. 3	综合判定：合格。			
18	GX-B1416/22-2-23024	2023. 7. 3	综合判定：合格。			


19	GX-B1416/22-2-23025	2023. 7. 3	综合判定：合格。	 2023/06/13
20	GX-B1310/21-2-23115	2023. 7. 1	符合标准要求。	 2023/06/06
21	GX-B1310/21-2-23116	2023. 7. 1	符合标准要求。	 2023/06/06

22	GX-B1310/21-2-23117	2023. 7. 1	符合标准要求。	
23	GX-B1310/21-2-23118	2023. 7. 1	符合标准要求。	
24	GX-B1310/21-2-23119	2023. 7. 1	符合标准要求。	

25	GX-B1310/21-2-23120	2023. 7. 1	符合标准要求。	 <p>2023/06/07</p>
26	GX-B1310/21-2-23121	2023. 7. 1	符合标准要求。	 <p>2023/06/08</p>
27	GX-B1310/21-2-23122	2023. 7. 1	符合标准要求。	 <p>2023/06/08</p>


28	GX-B1310/21-2-23123	2023. 7. 1	符合标准要求。	
29	GX-B1598/21-2-23052	2023. 7. 1	实测钢丝绳有效截面积 损失百分比最大为 0.44%，小于5%为正常。	
30	GX-B1598/21-2-23053	2023. 7. 1	实测钢丝绳有效截面积 损失百分比最大为 0.41%，小于5%为正常。	

31	GX-B1598/21-2-23054	2023. 7. 1	实测钢丝绳有效截面积 损失百分比最大为 0.54%，小于5%为正常	
32	GX-B1598/21-2-23055	2023. 7. 1	实测钢丝绳有效截面积 损失百分比最大为 0.84%，小于5%为正常。	
33	GX-B1350/21-2-23028	2023. 7. 3	本次共检验接地装置 6处，6处所检项目合格 。	

34	GX-B1359/21-2-23038~23047	2023. 7. 1	本次共检矿用隔爆型照明信号综合保护装置10台, 10台所检项目合格。	
35	GX-B1359/21-2-23048~23054	2023. 7. 1	本次共检矿用隔爆型照明信号综合保护装置7台, 7台所检项目合格。	
36	GX-B1424/20-2-23008	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。	

37	GX-B1424/20-2-23009	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。			
38	GX-B1424/20-2-23010	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。			
39	GX-B1424/20-2-23011	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。			

40	GX-B1424/20-2-23012	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/06/12</p>
41	GX-B1424/20-2-23013	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/06/12</p>
42	GX-B1424/20-2-23014	2023. 7. 4	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/06/13</p>

43	GX-B1424/20-2-23015	2023. 7. 4	依据NB/T 10176-2019单 轨吊车所检项目合格。			
----	---------------------	------------	----------------------------------	--	---	--