

序号	报告编号	发布日期	结论	影像资料
320	GX-B1367/22-A-23077	2023/7/27	阻燃性不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1367/22-A-23083	2023/7/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
322	GX-B1367/22-A-23084	2023/7/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
323	GX-B1364/22-A-23617	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1364/22-A-23616	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1364/22-A-23615	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1364/22-A-23614	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
327	GX-B1364/22-A-23613	2023/7/28	所检项目合格。	 <p>The photograph shows two technicians in white uniforms with '信公检' (Xin Gong Jian) on the back, operating a large industrial machine. The machine has a control panel with red digital displays showing '000'. A date stamp '2023/07/14' is visible in the bottom right corner of the image. The machine has a yellow warning triangle on its front panel.</p>

序号	报告编号	发布日期	结论	影像资料
328	GX-B1364/22-A-23612	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1364/22-A-23611	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1364/22-A-23621	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1364/22-A-23620	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1364/22-A-23619	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
333	GX-B1364/22-A-23618	2023/7/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1364/22-A-23600	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1364/22-A-23602	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
336	GX-B1364/22-A-23601	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1364/22-A-23603	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1364/22-A-23604	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1364/22-A-23623	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1364/22-A-23651	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1364/22-A-23646	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1364/22-A-23645	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1364/22-A-23624	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1364/22-A-23647	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1364/22-A-23648	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1364/22-A-23650	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1364/22-A-23649	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1364/22-A-23625	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1509/20-A-23009	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1509/20-A-23008	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
351	GX-B1368/20-A-23003	2023/7/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1368/20-A-23004	2023/7/28	所检项目合格。	