

序号	报告编号	发布日期	结论	影像资料
18	GX-B1461/22-A-23003	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1363/22-A-23470	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1363/22-A-23472	2023/11/1	所检项目合格。	 A photograph showing two men in light-colored work jackets inspecting a large, rusted industrial furnace or boiler. One man is on the left, looking at the side of the unit, while the other is on the right, looking into an open door of the furnace. The furnace has a tall, cylindrical chimney pipe extending from the top. The room has a window with a red frame and a white fan on the wall to the right. A date stamp '2023/10/22' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
21	GX-B1364/22-A-231006	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1364/22-A-231007	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1364/22-A-231008	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1364/22-A-231010	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1364/22-A-231011	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1364/22-A-231035	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-231036	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-231037	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1364/22-A-231038	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-231039	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-231040	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1364/22-A-231009	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1364/22-A-231022	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1364/22-A-231023	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1364/22-A-231024	2023/11/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1363/22-A-23501	2023/11/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1364/22-A-231005	2023/11/2	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1363/22-A-23494	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1509/20-A-23015	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1364/22-A-23973	2023/11/3	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1364/22-A-23970	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/22-A-23971	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1364/22-A-23972	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1364/22-A-23975	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1364/22-A-23976	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
45	GX-B1364/22-A-23977	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1364/22-A-23978	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1364/22-A-23979	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1364/22-A-23967	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
49	GX-B1364/22-A-23974	2023/11/3	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1363/22-A-23492	2023/11/3	全厚度拉断为 1027N/mm；拉断伸长率为 30%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
51	GX-B1363/22-A-23493	2023/11/3	全厚度拉断为 1009N/mm; 拉断伸长率为 24%; 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1363/22-A-23486	2023/11/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
53	GX-B1363/22-A-23487	2023/11/6	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
54	GX-B1364/22-A-231012	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
55	GX-B1364/22-A-231013	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1364/22-A-231014	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
57	GX-B1364/22-A-231015	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1364/22-A-231016	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
59	GX-B1364/22-A-231017	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
60	GX-B1363/22-A-23480	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
61	GX-B1363/22-A-23491	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1364/22-A-23997	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
63	GX-B1364/22-A-23983	2023/11/7	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1364/22-A-231027	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1364/22-A-231034	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1364/22-A-231033	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1364/22-A-231030	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1364/22-A-231029	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
69	GX-B1364/22-A-231028	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1364/22-A-231032	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
71	GX-B1364/22-A-231031	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1364/22-A-231026	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
73	GX-B1364/22-A-231018	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1364/22-A-231019	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1364/22-A-231020	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
76	GX-B1364/22-A-231021	2023/11/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
77	GX-B1364/22-A-23998	2023/11/7	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1364/22-A-23999	2023/11/7	所检项目合格。	