





序号	报告编号	发布日期	结论	影像资料
158	GX-B1423/20-Y-236179	2023年11月16日	综合判定：合格	
159	GX-B1423/20-Y-236180	2023年11月16日	综合判定：合格	

160	GX-B1423/20-Y-236181	2023年11月16日	综合判定：合格	
161	GX-B1423/20-Y-236182	2023年11月16日	综合判定：合格	
162	GX-B1423/20-Y-236183	2023年11月16日	综合判定：合格	

163	GX-B1423/20-Y-236184	2023年11月16日	综合判定：合格	
164	GX-B1423/20-Y-236185	2023年11月16日	综合判定：合格	
165	GX-B1423/20-Y-236186	2023年11月16日	综合判定：合格	

166	GX-B1423/20-Y-236187	2023年11月16日	综合判定：合格	 <p>2023/10/25</p>
167	GX-B1423/20-Y-236188	2023年11月16日	综合判定：合格	 <p>2023/10/25</p>
168	GX-B1423/20-Y-236189	2023年11月16日	综合判定：合格	 <p>2023/10/25</p>




169	GX-B1423/20-Y-236190	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with the identification number MX2018 is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The date 2023/10/25 is visible in the bottom right corner of the image.</p>
170	GX-B1423/20-Y-236191	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with the identification number MX2019 is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The date 2023/10/25 is visible in the bottom right corner of the image.</p>
171	GX-B1423/20-Y-236192	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with the identification number MX2020 is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The date 2023/10/25 is visible in the bottom right corner of the image.</p>

172	GX-B1423/20-Y-236193	2023年11月16日	综合判定：合格	 A yellow dump truck with the license plate MX2021 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/10/25 is visible in the bottom right corner of the photo.
173	GX-B1423/20-Y-236194	2023年11月16日	综合判定：合格	 An orange dump truck is parked on a dirt surface. Three workers in safety gear are standing next to it. The date 2023/10/25 is visible in the bottom right corner of the photo.
174	GX-B1423/20-Y-236195	2023年11月16日	综合判定：合格	 A yellow dump truck with the license plate MX2021 is parked on a dirt surface. Two workers in safety gear are standing next to it. The date 2023/10/25 is visible in the bottom right corner of the photo.




175	GX-B1423/20-Y-236196	2023年11月16日	综合判定：合格	
176	GX-B1423/20-Y-236197	2023年11月16日	综合判定：合格	
177	GX-B1423/20-Y-236198	2023年11月16日	综合判定：合格	




178	GX-B1423/20-Y-236199	2023年11月16日	综合判定：合格	 A yellow XCMG MX2303 dump truck is shown from a front-three-quarter view. Two workers in safety gear stand in front of the truck. The truck has 'MX2303' on the front and 'XCMG' and 'MX2303' on the side. A timestamp '2023/10/26' is in the bottom right corner.
179	GX-B1423/20-Y-236200	2023年11月16日	综合判定：合格	 A yellow XCMG MX2306 dump truck is shown from a front-three-quarter view. Two workers in safety gear stand in front of the truck. The truck has 'MX2306' on the front and 'XCMG' and 'MX2306' on the side. A timestamp '2023/10/26' is in the bottom right corner.
180	GX-B1423/20-Y-236201	2023年11月16日	综合判定：合格	 A yellow XCMG MX2307 dump truck is shown from a front-three-quarter view. Two workers in safety gear stand in front of the truck. The truck has 'MX2307' on the front and 'XCMG' and 'MX2307' on the side. A timestamp '2023/10/26' is in the bottom right corner.

181	GX-B1423/20-Y-236202	2023年11月16日	综合判定：合格	 A yellow XCMG MX2299 truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The date 2023/10/26 is visible in the bottom right corner of the photo.
182	GX-B1423/20-Y-236203	2023年11月16日	综合判定：合格	 A yellow XCMG MX2305 truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The date 2023/10/26 is visible in the bottom right corner of the photo.
183	GX-B1423/20-Y-236204	2023年11月16日	综合判定：合格	 A yellow XCMG MX2305 truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The date 2023/10/26 is visible in the bottom right corner of the photo.

184	GX-B1423/20-Y-236205	2023年11月16日	综合判定：合格	
185	GX-B1423/20-Y-236206	2023年11月16日	综合判定：合格	
186	GX-B1423/20-Y-236207	2023年11月16日	综合判定：合格	

187	GX-B1423/20-Y-236208	2023年11月16日	综合判定：合格	 <p>A yellow MAZ267 DW105A dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/10/26' is visible in the bottom right corner of the photo.</p>
188	GX-B1423/20-Y-236209	2023年11月16日	综合判定：合格	 <p>A yellow MAZ267 DW105A dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/10/26' is visible in the bottom right corner of the photo.</p>
189	GX-B1423/20-Y-236210	2023年11月16日	综合判定：合格	 <p>A yellow MAZ268 DW105A dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The date stamp '2023/10/26' is visible in the bottom right corner of the photo.</p>




190	GX-B1423/20-Y-236211	2023年11月16日	综合判定：合格	
191	GX-B1423/20-Y-236212	2023年11月16日	综合判定：合格	
192	GX-B1423/20-Y-236213	2023年11月16日	综合判定：合格	

193	GX-B1423/20-Y-236214	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX214 and DW105A is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/10/27' is visible in the bottom right corner of the photo.
194	GX-B1423/20-Y-236215	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX215 and DW105A is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/10/27' is visible in the bottom right corner of the photo.
195	GX-B1423/20-Y-236216	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX216 and DW105A is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/10/27' is visible in the bottom right corner of the photo.

196	GX-B1423/20-Y-236217	2023年11月16日	综合判定：合格	
197	GX-B1423/20-Y-236218	2023年11月16日	综合判定：合格	
198	GX-B1423/20-Y-236219	2023年11月16日	综合判定：合格	

199	GX-B1423/20-Y-236220	2023年11月16日	综合判定：合格	
200	GX-B1423/20-Y-236221	2023年11月16日	综合判定：合格	
201	GX-B1423/20-Y-236222	2023年11月16日	综合判定：合格	

202	GX-B1423/20-Y-236223	2023年11月16日	综合判定：合格	
203	GX-B1423/20-Y-236224	2023年11月16日	综合判定：合格	
204	GX-B1423/20-Y-236225	2023年11月16日	综合判定：合格	

205	GX-B1423/20-Y-236226	2023年11月16日	综合判定：合格	
206	GX-B1423/20-Y-236227	2023年11月16日	综合判定：合格	
207	GX-B1423/20-Y-236228	2023年11月16日	综合判定：合格	




208	GX-B1423/20-Y-236229	2023年11月16日	综合判定：合格	 <p>A yellow Xigao MX2263 dump truck is shown from a side profile. Two workers in safety gear stand in front of the truck. The truck has 'XIGAO' and 'MX2263' visible on its side. A yellow timestamp '2023/10/27' is in the bottom right corner.</p>
209	GX-B1423/20-Y-236230	2023年11月16日	综合判定：合格	 <p>A yellow Xigao MX2263 dump truck is shown from a side profile. Two workers in safety gear stand in front of the truck. The truck has 'XIGAO' and 'MX2263' visible on its side. A yellow timestamp '2023/10/27' is in the bottom right corner.</p>
210	GX-B1423/20-Y-236231	2023年11月16日	综合判定：合格	 <p>A yellow Xigao MX2240 dump truck is shown from a front-quarter view. Two workers in safety gear stand in front of the truck. The truck has 'XIGAO' and 'MX2240' visible on its side. A yellow timestamp '2023/10/27' is in the bottom right corner.</p>

211	GX-B1423/20-Y-236232	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2243 is shown in a desert-like environment. Two workers in blue uniforms and red hard hats are standing next to the truck. A yellow timestamp '2023/10/28' is visible in the bottom right corner of the image.
212	GX-B1423/20-Y-236233	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2254 is shown in a desert-like environment. A worker in a blue uniform and red hard hat is standing next to the truck. A yellow timestamp '2023/10/28' is visible in the bottom right corner of the image.
213	GX-B1423/20-Y-236234	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2241 is shown in a desert-like environment. Two workers in blue uniforms and red hard hats are standing next to the truck. A yellow timestamp '2023/10/28' is visible in the bottom right corner of the image.

214	GX-B1423/20-Y-236235	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with license plate MX2246 is parked on a dirt surface. Two workers in blue uniforms and hard hats are standing next to the truck. A date stamp '2023/10/28' is visible in the bottom right corner of the image.</p>
215	GX-B1423/20-Y-236236	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with license plate MX2205 is parked on a dirt surface. Two workers in blue uniforms and hard hats are standing next to the truck. A date stamp '2023/10/28' is visible in the bottom right corner of the image.</p>
216	GX-B1423/20-Y-236237	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with license plate MX2251 is parked on a dirt surface. Two workers in blue uniforms and hard hats are standing next to the truck. A date stamp '2023/10/28' is visible in the bottom right corner of the image.</p>

217	GX-B1423/20-Y-236238	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2249 is shown. Two workers wearing hard hats and safety gear are standing in front of the truck. The date 2023/10/28 is visible in the bottom right corner of the photo.
218	GX-B1423/20-Y-236239	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2250 is shown. Two workers wearing hard hats and safety gear are standing in front of the truck. The date 2023/10/28 is visible in the bottom right corner of the photo.
219	GX-B1423/20-Y-236240	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2255 is shown. Two workers wearing hard hats and safety gear are standing in front of the truck. The date 2023/10/28 is visible in the bottom right corner of the photo.

220	GX-B1423/20-Y-236241	2023年11月16日	综合判定：合格	
221	GX-B1423/20-Y-236242	2023年11月16日	综合判定：合格	
222	GX-B1423/20-Y-236243	2023年11月16日	综合判定：合格	

223	GX-B1423/20-Y-236244	2023年11月16日	综合判定：合格	
224	GX-B1423/20-Y-236245	2023年11月16日	综合判定：合格	
225	GX-B1423/20-Y-236246	2023年11月16日	综合判定：合格	

226	GX-B1423/20-Y-236247	2023年11月16日	综合判定：合格	
227	GX-B1423/20-Y-236248	2023年11月16日	综合判定：合格	
228	GX-B1423/20-Y-236249	2023年11月16日	综合判定：合格	

229	GX-B1423/20-Y-236250	2023年11月16日	综合判定：合格	 <p>A yellow XCMG MX259 dump truck is shown from a front-three-quarter view. Two workers wearing hard hats and work clothes stand in front of the truck. The truck has 'MX259' and 'XCMG' visible on its side. A date stamp '2023/10/29' is in the bottom right corner.</p>
230	GX-B1423/20-Y-236251	2023年11月16日	综合判定：合格	 <p>A side view of a yellow dump truck. Two workers are standing near the rear of the truck. The truck has 'XCMG' visible on its side. A date stamp '2023/10/29' is in the bottom right corner.</p>
231	GX-B1423/20-Y-236252	2023年11月16日	综合判定：合格	 <p>A yellow dump truck with its bed raised. Two workers are standing in front of the truck. The truck has 'XCMG' visible on its side. A date stamp '2023/10/29' is in the bottom right corner.</p>

232	GX-B1423/20-Y-236253	2023年11月16日	综合判定：合格	
233	GX-B1423/20-Y-236254	2023年11月16日	综合判定：合格	
234	GX-B1423/20-Y-236255	2023年11月16日	综合判定：合格	

235	GX-B1423/20-Y-236256	2023年11月16日	综合判定：合格	
236	GX-B1423/20-Y-236257	2023年11月16日	综合判定：合格	
237	GX-B1423/20-Y-236258	2023年11月16日	综合判定：合格	

238	GX-B1423/20-Y-236259	2023年11月16日	综合判定：合格	 <p>A yellow XCMG XE271 dump truck is shown from a side-rear perspective. The truck is parked on a dirt surface. Two workers in safety gear are standing near the rear of the truck. The date '2023/10/29' is visible in the bottom right corner of the photo.</p>
239	GX-B1423/20-Y-236260	2023年11月16日	综合判定：合格	 <p>A yellow XCMG XE271 dump truck is shown from a side-front perspective. The truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date '2023/10/29' is visible in the bottom right corner of the photo.</p>
240	GX-B1423/20-Y-236261	2023年11月16日	综合判定：合格	 <p>A yellow XCMG XE271 dump truck is shown from a side-front perspective. The truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date '2023/10/29' is visible in the bottom right corner of the photo.</p>

241	GX-B1423/20-Y-236262	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2273 on its side. Two workers in safety gear are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/10/29' is visible in the bottom right corner of the photo.
242	GX-B1423/20-Y-236263	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2275 on its side. Two workers in safety gear are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/10/29' is visible in the bottom right corner of the photo.
243	GX-B1423/20-Y-236264	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2274 on its side. Two workers in safety gear are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/10/29' is visible in the bottom right corner of the photo.




244	GX-B1423/20-Y-236265	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2269 and '2269' on the side. Two workers in safety gear stand in front of it. The date stamp '2023/10/29' is in the bottom right corner.
245	GX-B1423/20-Y-236266	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2270 and '2270' on the side. Two workers in safety gear stand in front of it. The date stamp '2023/10/29' is in the bottom right corner.
246	GX-B1423/20-Y-236267	2023年11月16日	综合判定：合格	 A yellow dump truck with the identification number MX2276 and '2276' on the side. Two workers in safety gear stand in front of it. The date stamp '2023/10/30' is in the bottom right corner.

247	GX-B1423/20-Y-236268	2023年11月16日	综合判定：合格	
248	GX-B1423/20-Y-236269	2023年11月16日	综合判定：合格	
249	GX-B1423/20-Y-236270	2023年11月16日	综合判定：合格	

250	GX-B1423/20-Y-236271	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>
251	GX-B1423/20-Y-236272	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>
252	GX-B1423/20-Y-236273	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>

253	GX-B1423/20-Y-236274	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>
254	GX-B1423/20-Y-236275	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>
255	GX-B1423/20-Y-236276	2023年11月16日	综合判定：合格	 <p>2023/10/30</p>

256	GX-B1423/20-Y-236277	2023年11月16日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front. The license plate reads GX-B1423. A timestamp '2023/10/30' is visible in the bottom right corner.</p>
257	GX-B1423/20-Y-236278	2023年11月16日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front. The license plate reads GX-B1423. A timestamp '2023/10/30' is visible in the bottom right corner.</p>
258	GX-B1423/20-Y-236279	2023年11月16日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front. The license plate reads GX-B1423. A timestamp '2023/10/30' is visible in the bottom right corner.</p>

259	GX-B1423/20-Y-236280	2023年11月16日	综合判定：合格	
260	GX-B1423/20-Y-236281	2023年11月16日	综合判定：合格	
261	GX-B1423/20-Y-236282	2023年11月16日	综合判定：合格	

262	GX-B1423/20-Y-236283	2023年11月16日	综合判定：合格	
263	GX-B1423/20-Y-236284	2023年11月16日	综合判定：合格	
264	GX-B1423/20-Y-236285	2023年11月16日	综合判定：合格	