


序号	报告编号	发布日期	结论	影像资料
14	GX-B1378/22-F-23243	2023. 11. 15	所检项目合格	 A photograph showing two female lab technicians in white coats standing in a laboratory. They are positioned near a table with various items on it. In the background, there is a window with orange curtains and a blue door. A small timestamp '2023/11/9' is visible in the bottom right corner of the image.
15	GX-B1377/22-F-23293	2023. 11. 15	所检项目合格	 A photograph showing two female lab technicians in white coats standing in a laboratory. They are positioned near a table with various items on it. In the background, there is a window with orange curtains and a blue door. A small timestamp '2023/11/13' is visible in the bottom right corner of the image.

16	GX-B1378/22-F-23244	2023. 11. 15	所检项目合格	
17	GX-B1378/22-F-23245~F-23246	2023. 11. 7	所检项目合格	
18	GX-B1378/22-F-23247	2023. 11. 20	所检项目合格	

19	GX-B1377/22-F-23294	2023. 11. 20	所检项目合格	 A photograph showing two laboratory technicians in white coats and masks working in a laboratory. They are standing at a table with various pieces of scientific equipment, including a large white machine and a computer monitor. The date 2023.11.16 is visible in the bottom right corner of the image.
----	---------------------	--------------	--------	---