

序号	报告编号	发布日期	结论	影像资料
37	GX-B1559/22-Y-23021	2023年12月15日	所检项目合格。	
38	GX-B1559/22-Y-23022	2023年12月15日	所检项目合格。	

39	GX-B1559/22-Y-23023	2023年12月15日	所检项目合格。	
40	GX-B1559/22-Y-23024	2023年12月15日	所检项目合格。	



41	GX-B1310/21-Y-23151	2023年12月15日	符合标准要求。	
42	GX-B1310/21-Y-23152	2023年12月15日	符合标准要求。	

43	GX-B1310/21-Y-23153	2023年12月15日	符合标准要求。	 <p>A photograph showing a worker in a blue uniform and a red helmet with a headlamp. The worker is focused on a task, possibly inspecting or adjusting a blue machine or component. The background shows a workshop environment with various tools and equipment. A yellow timestamp '2023/11/20' is visible in the bottom right corner of the image.</p>
44	GX-B1310/21-Y-23154	2023年12月15日	符合标准要求。	 <p>A photograph showing a worker in a dark uniform and a red helmet with a headlamp. The worker is working in a dark environment, possibly a confined space or a tunnel. The worker's hands are visible, and they appear to be handling a component or tool. A yellow timestamp '2023/11/20' is visible in the bottom right corner of the image.</p>

45	GX-B1310/21-Y-23155	2023年12月15日	符合标准要求。	 A photograph showing a worker in a blue uniform and red helmet operating machinery. The worker is standing on a platform, looking at a large blue cylindrical component. A yellow timestamp '2023/11/20' is visible in the bottom right corner of the image.
46	GX-B1310/21-Y-23160	2023年12月15日	符合标准要求。	 A photograph showing a worker in an orange uniform operating machinery. The worker is wearing a red helmet and is positioned in a complex industrial environment with various pipes and components. A yellow timestamp '2023/11/24' is visible in the bottom right corner of the image.

47	GX-B1424/20-Y-23014	2023年12月15日	依据NB/T 10176-2019单轨吊车综合判定合格。	
48	GX-B1417/22-Y-23103	2023年12月14日	所检项目合格。	

49	GX-B1417/22-Y-23104	2023年12月14日	所检项目合格。	 A photograph showing two workers in safety gear (hard hats and work clothes) inspecting equipment in a workshop or industrial setting. The date stamp '2023/12/6' is visible in the bottom right corner of the image.
50	GX-B1417/22-Y-23105	2023年12月14日	所检项目合格。	 A photograph showing two workers in safety gear standing next to a white truck. The truck has the number '8' and 'K5' visible on its side. The date stamp '2023/12/6' is visible in the bottom right corner of the image.

51	GX-B1417/22-Y-23106	2023年12月14日	所检项目合格。	
52	GX-B1417/22-Y-23107	2023年12月14日	所检项目合格。	

53	GX-B1417/22-Y-23108	2023年12月14日	所检项目合格。	
54	GX-B1417/22-Y-23109	2023年12月14日	所检项目合格。	

55	GX-B1417/22-Y-23110	2023年12月14日	所检项目合格。	
56	GX-B1417/22-Y-23111	2023年12月14日	所检项目合格。	

57	GX-B1417/22-Y-23112	2023年12月14日	所检项目合格。	
58	GX-B1417/22-Y-23113	2023年12月14日	所检项目合格。	

59	GX-B1417/22-Y-23114	2023年12月14日	所检项目合格。	
60	GX-B1417/22-Y-23115	2023年12月14日	所检项目合格。	

61	GX-B1300/23-Y-23013	2023年12月20日	综合判定：合格。	 <p>2023/11/21</p>
62	GX-B1300/23-Y-23014	2023年12月20日	综合判定：合格。	 <p>2023/11/21</p>

63	GX-B1521/20-Y-23629	2023年12月20日	所检项目合格。	
64	GX-B1521/20-Y-23630	2023年12月20日	所检项目合格。	



65	GX-B1521/20-Y-23631	2023年12月20日	所检项目合格。	
66	GX-B1539/22-Y-23275	2023年12月20日	所检项目合格。	

67	GX-B1328/20-Y-23158	2023年12月19日	本次共检绝缘手套84只，84只绝缘手套所检项目合格。	
68	GX-B1328/20-Y-23159	2023年12月19日	本次共检绝缘鞋114只，114只绝缘鞋所检项目合格。	

69	GX-B1328/20-Y-23160	2023年12月19日	本次共检验电器30支，30支验电器合格。	
70	GX-B1328/20-Y-23161	2023年12月19日	本次共检携带式接地和接地短路装置15组，15组携带式接地和接地短路装置所检项目合格。	

71	GX-B1328/20-Y-23162	2023年12月19日	本次共检绝缘杆2组，2组绝缘杆合格。
72	GX-B1328/20-Y-23165	2023年12月20日	本次共检绝缘胶垫5件，5件绝缘胶垫合格。



73	GX-B1328/20-Y-23155	2023年12月19日	本次共检绝缘手套14只，14只绝缘手套所检项目合格。	
74	GX-B1328/20-Y-23156	2023年12月19日	本次共检绝缘鞋20只，20只绝缘鞋所检项目合格。	

75	GX-B1328/20-Y-23157	2023年12月19日	所检项目合格。	
76	GX-B1328/20-Y-23166	2023年12月19日	本次共检验电器3支，3支 验电器合格。	



77	GX-B1521/20-Y-23632	2023年12月20日	所检项目合格。	
78	GX-B1521/20-Y-23633	2023年12月20日	所检项目合格。	

79	GX-B1539/22-Y-23276	2023年12月20日	所检项目合格。	
80	GX-B1517/20-Y-23027	2023年12月20日	综合判定：合格。	



81	GX-B1310/21-Y-23161	2023年12月20日	符合标准要求。	 A photograph of a worker wearing a red hard hat, a white face mask, and a camouflage jacket. The worker is holding a handheld electronic device and looking at it. The background is dark, suggesting an industrial or construction site at night. A yellow timestamp '2023/12/7' is visible in the bottom right corner of the image.
82	GX-B1310/21-Y-23162	2023年12月20日	符合标准要求。	 A photograph of a worker wearing a red hard hat, a white face mask, and a camouflage jacket. The worker is standing in an industrial environment, possibly a factory or construction site, with various pieces of equipment and structures visible in the background. A yellow timestamp '2023/12/7' is visible in the bottom right corner of the image.

83	GX-B1310/21-Y-23163	2023年12月20日	符合标准要求。	
84	GX-B1310/21-Y-23164	2023年12月20日	符合标准要求。	

85	GX-B1310/21-Y-23165	2023年12月20日	符合标准要求。	 <p>2023/12/7</p>
86	GX-B1310/21-Y-23166	2023年12月20日	符合标准要求。	 <p>2023/12/7</p>

87	GX-B1310/21-Y-23167	2023年12月20日	符合标准要求。	 A worker wearing a white protective suit, a red hard hat, and a white face mask is standing in a room with blue walls. The worker is looking down at a handheld device or control panel. The date '2023/12/7' is visible in the bottom right corner of the photo.
88	GX-B1310/21-Y-23168	2023年12月20日	符合标准要求。	 A worker wearing a white protective suit, a red hard hat, and a white face mask is operating a large piece of machinery in a room with blue walls. The worker is looking at the machinery. The date '2023/12/7' is visible in the bottom right corner of the photo.

89	GX-B1310/21-Y-23169	2023年12月20日	符合标准要求。	
90	GX-B1310/21-Y-23170	2023年12月20日	符合标准要求。	

91	GX-B1310/21-Y-23171	2023年12月20日	符合标准要求。	 A worker wearing a grey protective suit, a red helmet, and a white face mask is working on a blue industrial machine. The worker is using a tool to work on a component of the machine. A yellow date stamp '2023/12/7' is visible in the bottom right corner of the image.
92	GX-B1310/21-Y-23172	2023年12月20日	符合标准要求。	 A worker wearing a grey protective suit, a red helmet, and a white face mask is working on a blue industrial machine. The worker is using a tool to work on a component of the machine. A yellow date stamp '2023/12/7' is visible in the bottom right corner of the image.

93	GX-B1310/21-Y-23173	2023年12月20日	符合标准要求。	 A worker wearing a red hard hat and a grey protective suit is working on a metal structure. The worker is holding a clipboard and looking at it. The background is dark and industrial. A yellow timestamp '2023/12/7' is visible in the bottom right corner of the photo.
94	GX-B1310/21-Y-23174	2023年12月20日	符合标准要求。	 A worker wearing a red hard hat and a grey protective suit is working on a large, blue-painted metal component. The worker is holding a clipboard and looking at it. The background is dark and industrial. A yellow timestamp '2023/12/7' is visible in the bottom right corner of the photo.

95	GX-B1310/21-Y-23175	2023年12月20日	符合标准要求。	 <p>A worker wearing a grey protective suit, a red helmet, and a white face mask is working on a yellow metal structure. The worker is positioned on the right side of the frame, facing left. The background is dark, and there are some mechanical components visible. A yellow date stamp '2023/12/7' is located in the bottom right corner of the image.</p>
96	GX-B1310/21-Y-23176	2023年12月20日	符合标准要求。	 <p>A worker wearing a dark protective suit, a red helmet, and a white face mask is working on a blue machine. The worker is positioned on the left side of the frame, facing right. The machine has various pipes and components. A yellow date stamp '2023/12/7' is located in the bottom right corner of the image.</p>

97	GX-B1310/21-Y-23177	2023年12月20日	符合标准要求。	 <p>2023/12/7</p>
98	GX-B1310/21-Y-23178	2023年12月20日	符合标准要求。	 <p>2023/12/7</p>

99	GX-B1310/21-Y-23179	2023年12月20日	符合标准要求。	 A worker wearing a grey uniform and a red hard hat is focused on adjusting a large, dark-colored industrial component, possibly a valve or part of a pump. The background shows blue structural elements of the machinery. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the photo.
100	GX-B1310/21-Y-23180	2023年12月20日	符合标准要求。	 A worker in a grey uniform and red hard hat is working on a piece of industrial equipment, possibly a control panel or a valve. The worker is wearing safety glasses and is looking intently at the equipment. The background is a light blue wall. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the photo.

101	GX-B1310/21-Y-23181	2023年12月20日	符合标准要求。	 <p>A worker wearing a red helmet, safety glasses, and a light-colored protective suit with reflective stripes is working on a large, dark industrial component. The worker is holding a tool and appears to be inspecting or measuring the component. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.</p>
102	GX-B1310/21-Y-23182	2023年12月20日	符合标准要求。	 <p>A worker wearing a red helmet, safety glasses, and a light-colored protective suit with reflective stripes is working on a large, dark industrial component. The worker is holding a tool and appears to be inspecting or measuring the component. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.</p>

103	GX-B1310/21-Y-23183	2023年12月20日	符合标准要求。	 A worker wearing a red safety helmet, safety glasses, and a grey protective suit is using a handheld electronic device. The worker is standing in an industrial environment with blue metal structures. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the photo.
104	GX-B1310/21-Y-23184	2023年12月20日	符合标准要求。	 A worker wearing a red safety helmet, safety glasses, and a grey protective suit is using a handheld electronic device. The worker is standing in an industrial environment with blue metal structures. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the photo.

105	GX-B1310/21-Y-23185	2023年12月20日	符合标准要求。	 A photograph showing a worker in a red hard hat and white protective suit working on a large industrial vessel in a dark environment. The worker is positioned behind a metal safety fence. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.
106	GX-B1310/21-Y-23186	2023年12月20日	符合标准要求。	 A photograph showing a worker in a red hard hat and white protective suit working on a blue-painted metal structure. The worker is wearing a white mask and is focused on a task. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.

107	GX-B1310/21-Y-23187	2023年12月20日	符合标准要求。	 A worker wearing a red hard hat and a grey protective suit is working on a blue metal structure. The worker is positioned on a platform or scaffolding, and the background shows a blue wall and a window. A yellow timestamp "2023/12/8" is visible in the bottom right corner of the image.
108	GX-B1310/21-Y-23188	2023年12月20日	符合标准要求。	 A worker wearing a red hard hat and a grey protective suit is working on a metal structure. The worker is wearing a respirator mask and is focused on a task. The background shows a blue wall and a window. A yellow timestamp "2023/12/8" is visible in the bottom right corner of the image.

109	GX-B1310/21-Y-23189	2023年12月20日	符合标准要求。	 <p>2023/12/8</p>
110	GX-B1310/21-Y-23190	2023年12月20日	符合标准要求。	 <p>2023/12/8</p>

111	GX-B1310/21-Y-23191	2023年12月20日	符合标准要求。	
112	GX-B1310/21-Y-23192	2023年12月20日	符合标准要求。	

113	GX-B1310/21-Y-23193	2023年12月20日	符合标准要求。	 A worker wearing a red helmet and a grey protective suit is working on a large, dark cylindrical component. The worker is using a tool, possibly a flashlight or a specialized instrument, to inspect or work on the component. The background is dark, and there is a yellow timestamp '2023/12/8' in the bottom right corner of the photo.
114	GX-B1310/21-Y-23194	2023年12月20日	符合标准要求。	 A worker wearing a red helmet and a grey protective suit is working on a blue metal structure. The worker is using a tool, possibly a flashlight or a specialized instrument, to inspect or work on the structure. The background is dark, and there is a yellow timestamp '2023/12/8' in the bottom right corner of the photo.

115	GX-B1310/21-Y-23195	2023年12月20日	符合标准要求。	 <p>A worker wearing a red safety helmet and a white protective suit is using a handheld electronic device to inspect a piece of machinery. The date stamp in the bottom right corner of the image is 2023/12/8.</p>
116	GX-B1522/20-Y-23147	2023年12月21日	所检项目合格。	 <p>A worker wearing a yellow safety vest is standing next to a large piece of machinery on a construction site. The date stamp in the bottom right corner of the image is 2023/12/8.</p>

117	GX-B1522/20-Y-23148	2023年12月21日	所检项目合格。	 A close-up photograph of a worker wearing a grey long-sleeved shirt, a high-visibility yellow safety vest, and a white face mask. The worker is seated and looking down at a handheld device or control panel. The background shows the interior of a piece of heavy machinery with various mechanical parts and a metal railing. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.
118	GX-B1522/20-Y-23149	2023年12月21日	所检项目合格。	 A photograph of a large, vertical drilling rig or core drill mounted on a tracked vehicle. The rig is yellow and black. A worker in a high-visibility vest and hard hat stands next to the rig. The background shows a construction site with a grey, overcast sky and some distant structures. A yellow timestamp '2023/12/8' is visible in the bottom right corner of the image.

119	GX-B1522/20-Y-23150	2023年12月21日	所检项目合格。	
120	GX-B1522/20-Y-23151	2023年12月21日	所检项目合格。	

121	GX-B1522/20-Y-23152	2023年12月21日	所检项目合格。
-----	---------------------	-------------	---------

