



序号	报告编号	发布日期	结论	影像资料
1	GX-B1354/20-6-23010	2024/1/3	电网接地电容电流符合规定	 A photograph showing a worker in a red hard hat and dark jacket operating a yellow device in front of electrical control panels. The panels have labels like '1003', '1005', and '1007'. A red sign with the word '运行' (Running) is visible. The date '2023 12 09' is in the bottom right corner.
2	GX-B1350/21-6-23053	2024/1/3	所检项目合格	 A photograph showing a worker in a red hard hat and dark jacket standing in a tunnel. The tunnel has yellow pipes and a blue light source. The date '2023 12 07' is in the bottom right corner.



3	GX-B1306/21-6-23020	2024/1/3	除部分问题外， 其余所检项目合格	 A man in a black jacket is working on a blue electrical cabinet. He is standing on a red step ladder. The photo has a timestamp of 2023.12.16.
4	GX-B1306/21-6-23021	2024/1/3	除部分问题外， 其余所检项目合格	 A man in a black jacket is working on a blue electrical cabinet. He is standing on a metal platform. The photo has a timestamp of 2023.12.16.
5	GX-B1307/20-6-23062	2024/1/3	综合判定合格	 Two workers in safety gear (blue and orange) are inspecting equipment. One worker is holding a white cylindrical object. The photo has a timestamp of 2024.2.13.

6	GX-B1307/20-6-23063	2024/1/3	综合判定合格	 <p>2023.12.13</p>
7	GX-B1307/20-6-23064	2024/1/3	综合判定合格	 <p>2023.12.14</p>
8	GX-B1307/20-6-23065	2024/1/3	综合判定合格	 <p>2023.12.14</p>

9	GX-B1307/20-6-23066	2024/1/3	综合判定合格	
10	GX-B1307/20-6-23067	2024/1/3	综合判定合格	
11	GX-B1520/20-6-23124	2024/1/3	综合判定合格	

12	GX-B13535/21-6-23001	2024/1/3	所检项目合格	 <p>2023 12 13</p>
13	GX-B1314/21-6-23004~23006	2024/1/3	所检项目合格	 <p>2023 12 08</p>
14	GX-B1382/21-6-23036	2024/1/4	合格	 <p>2023 12 16</p>

15	GX-B1305/21-6-23023	2024/1/4	综合判定合格	
16	GX-B1307/20-6-23068	2024/1/4	综合判定合格	
17	GX-B1520/20-6-23126	2024/1/4	综合判定：合格	

18	GX-B1520/20-6-23127	2024/1/4	综合判定：合格	
19	GX-B1520/20-6-23128	2024/1/4	综合判定：合格	
20	GX-B1520/20-6-23125	2024/1/4	综合判定：合格	