



序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/21-9-24001	2024年2月5日	综合判定：合格。	
2	GX-B1341/21-9-24002	2024年2月5日	综合判定：合格。	
3	GX-B1341/21-9-24003	2024年2月5日	综合判定：合格。	
4	GX-B1341/21-9-24004	2024年2月5日	综合判定：合格。	

5	GX-B1341/21-9-24005	2024年2月5日	综合判定：合格。	
6	GX-B1341/21-9-24006	2024年2月5日	综合判定：合格。	
7	GX-B1341/21-9-24007	2024年2月5日	综合判定：合格。	
8	GX-B1341/21-9-24008	2024年2月5日	综合判定：合格。	



9	GX-B1341/21-9-24009	2024年2月5日	综合判定：合格。	
10	GX-B1341/21-9-24010	2024年2月5日	综合判定：合格。	
11	GX-B1341/21-9-24011	2024年2月5日	综合判定：合格。	
12	GX-B1341/21-9-24031	2024年2月5日	风机反风率为68.6%，综合判定：合格。	

13	GX-B1341/21-9-24032	2024年2月5日	风机反风率为63.9%，综合判定：合格。	
14	GX-B1341/21-9-24033	2024年2月5日	风机反风率为63.6%，综合判定：合格。	
15	GX-B1341/21-9-24034	2024年2月5日	风机反风率为64.2%，综合判定：合格。	
16	GX-B1341/21-9-24035	2024年2月5日	风机反风率为64.8%，综合判定：合格。	

17	GX-B1341/21-9-24036	2024年2月5日	风机反风率为68.3%，综合判定：合格。	
18	GX-B1341/21-9-24037	2024年2月5日	风机反风率为63.1%，综合判定：合格。	
19	GX-B1341/21-9-24038	2024年2月5日	风机反风率为63.4%，综合判定：合格。	
20	GX-B1341/21-9-24039	2024年2月5日	风机反风率为69.1%，综合判定：合格。	

21	GX-B1341/21-9-24040	2024年2月5日	风机反风率为70.0%，综合判定：合格。	
22	GX-B1341/21-9-24041	2024年2月5日	风机反风率为72.9%，综合判定：合格。	
23	GX-B1341/21-9-24012	2024.2.5	综合判定：合格。	

24	GX-B1341/21-9-24013	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow helmets standing in a tunnel. They are holding flashlights. The tunnel has a metal grate in the background. The date 2024-01-04 is visible in the bottom right corner of the image.	
25	GX-B1341/21-9-24014	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow helmets standing in a tunnel. They are holding flashlights. The tunnel has a metal grate in the background. The date 2024-01-04 is visible in the bottom right corner of the image.	

26	GX-B1341/21-9-24015	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow hard hats standing in a dark tunnel. The workers are facing the camera. A date stamp '2024-01-04' is visible in the bottom right corner of the image.	
27	GX-B1341/21-9-24016	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow hard hats standing in a dark tunnel. They are positioned next to a large, dark pipe. One worker is holding a flashlight. A date stamp '2024-01-04' is visible in the bottom right corner of the image.	





28	GX-B1341/21-9-24017	2024.2.5	综合判定：合格。			
29	GX-B1341/21-9-24018	2024.2.5	综合判定：合格。			

30	GX-B1341/21-9-24019	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow hard hats standing in a tunnel. They are positioned in front of a metal gate or barrier. The tunnel walls are dark and rocky. A date stamp '2024-01-04' is visible in the bottom right corner of the image.	
31	GX-B1341/21-9-24020	2024.2.5	综合判定：合格。		 A photograph showing two workers in red protective suits and yellow hard hats standing in a tunnel. They are positioned in front of a metal gate or barrier. The tunnel walls are dark and rocky. A date stamp '2024-01-04' is visible in the bottom right corner of the image.	

32	GX-B1341/21-9-24021	2024.2.6	综合判定：合格。	 <p>2024-01-05</p>
33	GX-B1341/21-9-24022	2024.2.5	综合判定：合格。	 <p>2024-01-05</p>

34	GX-B1341/21-9-24023	2024.2.5	综合判定：合格。	 <p>2024-01-05</p>
35	GX-B1341/21-9-24024	2024.2.5	综合判定：合格。	 <p>2024-01-05</p>

36	GX-B1341/21-9-24025	2024.2.5	综合判定：合格。	 <p>2024-01-05</p>
37	GX-B1341/21-9-24026	2024.2.5	综合判定：合格。	 <p>2024-01-05</p>

38	GX-B1341/21-9-24027	2024.2.5	综合判定：合格。	 <p>2024.1.6</p>
39	GX-B1341/21-9-24028	2024.2.5	综合判定：合格。	 <p>2024.1.6</p>



40	GX-B1341/21-9-24029	2024.2.5	综合判定：合格。	 <p>2024.1.6</p>
41	GX-B1341/21-9-24030	2024.2.5	综合判定：合格。	 <p>2024.1.6</p>

42	GX-B1341/21-9-24042	2024.2.5	风机反风率为63.3%，综合判定：合格。	 <p>2024-01-04</p>
43	GX-B1341/21-9-24043	2024.2.5	风机反风率为62.3%，综合判定：合格。	 <p>2024-01-04</p>



44	GX-B1341/21-9-24044	2024.2.5	风机反风率为64.2%，综合判定：合格。	 A photograph showing two workers in red protective suits and yellow hard hats standing in a dark tunnel. They are positioned in front of a circular opening, possibly a fan or a door. The tunnel walls are rough and rocky. A date stamp '2024-01-04' is visible in the bottom right corner of the image.
45	GX-B1341/21-9-24045	2024.2.5	风机反风率为62.9%，综合判定：合格。	 A photograph showing two workers in red protective suits and yellow hard hats standing in a dark tunnel. They are positioned in front of a circular opening, possibly a fan or a door. The tunnel walls are rough and rocky. A date stamp '2024-01-04' is visible in the bottom right corner of the image.

46	GX-B1341/21-9-24046	2024.2.5	风机反风率为 63.3%，综合判 定：合格。	
47	GX-B1341/21-9-24047	2024.2.5	风机反风率为 62.4%，综合判 定：合格。	

48	GX-B1341/21-9-24048	2024.2.5	风机反风率为62.5%，综合判定：合格。		 <p>2024-01-04</p>	
49	GX-B1341/21-9-24049	2024.2.5	风机反风率为65.8%，综合判定：合格。		 <p>2024-01-04</p>	

50	GX-B1341/21-9-24050	2024.2.5	风机反风率为 63.9%，综合判 定：合格。	
51	GX-B1341/21-9-24051	2024.2.5	风机反风率为 63.8%，综合判 定：合格。	

52	GX-B1341/21-9-24052	2024.2.5	风机反风率为 61.8%，综合判 定：合格。	 <p>2024-01-05</p>
53	GX-B1341/21-9-24053	2024.2.5	风机反风率为 61.4%，综合判 定：合格。	 <p>2024-01-05</p>


54	GX-B1341/21-9-24054	2024.2.5	风机反风率为64.3%，综合判定：合格。	 A photograph showing two workers in red uniforms and yellow hard hats standing in a tunnel. They are positioned next to a large, light-colored control panel or electrical cabinet. The tunnel walls are rough and rocky. A date stamp '2024-01-05' is visible in the bottom right corner of the image.
55	GX-B1341/21-9-24055	2024.2.5	风机反风率为64.1%，综合判定：合格。	 A photograph showing two workers in red uniforms and yellow hard hats standing in a tunnel. They are positioned in the center of the frame, facing the camera. The tunnel walls are dark and rocky. A date stamp '2024-01-05' is visible in the bottom right corner of the image.

56	GX-B1341/21-9-24056	2024.2.5	风机反风率为66.2%，综合判定：合格。	 <p>2024-01-05</p>
57	GX-B1341/21-9-24057	2024.2.5	风机反风率为67.8%，综合判定：合格。	



58	GX-B1341/21-9-24058	2024.2.5	风机反风率为61.2%，综合判定：合格。	
59	GX-B1341/21-9-24059	2024.2.5	风机反风率为67.8%，综合判定：合格。	



60	GX-B1341/21-9-24060	2024.2.5	风机反风率为63.0%，综合判定：合格。	
----	---------------------	----------	----------------------	---